

# Public Works Foreman Report

October 24, 2017

---

## 1) Roads

- a) Fill, grade and pack water and sewer install trench on 50 Ave between 51<sup>st</sup> and 52<sup>nd</sup> St.
- b) Gravel and grade back alley between 53<sup>rd</sup> St. and 54<sup>th</sup> St. south between 45 Ave and 46<sup>th</sup> Ave.
- c) Grade all other alleys as needed.
- d) Grade industrial park roads - 51<sup>st</sup> St. and 57<sup>th</sup> Ave.
- e) Fill potholes on 49<sup>th</sup> St. and 50<sup>th</sup> Ave.
- f) Install safety posts along ditch on the south end of 49<sup>th</sup> St.
- g) Remove asphalt from gutter on 47<sup>th</sup> Ave in front of Senior Center.
- h) Vacuum out culverts in back alley at 4708 47<sup>th</sup> St.

## 2) Water/Wastewater

- a) Attended ACE meeting and facility tour in Vegreville with CAO and Public Work Foreman.
- b) Prepared a short sanitary use consumption analysis over past winter months to assess infiltration issues during cold months for CAO.
- c) Shut off water to Geleta Park before exposed line freeze and rupture- blew out all lines with compressor, drained hot water tanks. – added RV antifreeze to all toilets and traps.
- d) Repaired Clubroom toilet at hall as per request.
- e) Water service and disconnect and reconnect as per administration request.
- f) Shut off water to RV dumping station for season.
- g) Check hydrant by county shop.
- h) Check flow between facultative and annual release lagoons.
- i) Check and vacuumed PRV vault.
- j) Continue to monitor south side water pressure.
- k) Follow up with Contech in regards to Variable Flow Device (VFD) off line at reservoir pump house from October 2<sup>nd</sup> power failure.
- l) Calibrated distribution CL2 analyser.
- m) Met with ACE operator and calibrated ACE 2 analyser in pump house.
- n) Routine pump house maintenance – check pump oil levels, etc.
- o) Began sanitary inspection and degreasing manholes and lifts station.

## 3) Other

- a) Install swimming pool sign on 52<sup>nd</sup> Ave and 51<sup>st</sup> St.
- b) Installed new lids and stoppers on garbage bins at 53<sup>rd</sup> Ave and 48<sup>th</sup> St.
- c) Load and haul garbage left next to red bin on 45<sup>th</sup> Ave and 52<sup>nd</sup> St.
- d) Removed all Canada banners from light poles on 51<sup>st</sup> St.
- e) Removed all business advertising banners.
- f) Band Christmas lights brackets and wrap rope light to light poles along 51<sup>st</sup> St.
- g) Service and mount sander on truck.
- h) Push up concrete at lagoon storage pad.
- i) Complete all service requests.